

Industry News

- Surgeson Electric is very proud to announce the opening of our 2nd branch in Ottawa. The branch will officially open on July 5, 2010.
- ABB hosted a seminar on Power correction capacitors. Many thanks to them for their excellent presentation. More product seminars to follow!
- We are pleased to announce that we are now stocking Waterway pool pumps. We also repair all makes & models.
- The Surgeson staff is presently enrolled in the Omron University Online courses.
- Summer shut downs are coming. Please contact Rodney for scheduling.
- Surgeson Electric is proud to be selected as Omron's Eastern Ontario Distributor.
- The Surgeson staff welcomes Bruce Surgeson. Bruce will be managing the Ottawa branch.

July / August 2010
Volume 2, Issue 2

Maintenance Tips!

Motor Surface Temperatures

Motor surface temperature is frequently of concern. The motor surface temperature will never exceed the internal temperature of the motor. However, depending upon the design and cooling arrangements in the motor, motor surface temperature in modern motors can be high enough to be very uncomfortable to the touch. Surface temperatures of 75° to 95°C can be found on T frame motor designs. These temperatures do not necessarily indicate overland or impending motor failure.

Monthly Specials



Pool & Spa Pumps



- REPAIR KITS' •
- JETS •
- POOL & SPA ACCESSORIES •



"If GM had kept up with technology like the computer industry had, we would be driving \$25 cars that get 1,000 MPG"
- Bill Gates -